



# JMV, JMVG, HT JMV & HT JMVG AXIALS

## WIRING DIAGRAM - 3022, 3020, 3018

CONNECTION DIAGRAM FOR THREE PHASE DELTA FIXED SPEED  
ACDE ROTATION


CONNECTION DIAGRAM FOR THREE PHASE DUAL VOLTAGE, STAR  
ACDE ROTATION



# JMV, JMVG, HT JMV & HT JMVG AXIALS

## WIRING DIAGRAM - 3022, 3020, 3018

FAN CONNECTED TO SPEED CONTROLLER (VARIABLE SPEED)



FAN CONNECTED TO SPEED CONTROLLER (VARIABLE SPEED)

