



ESTOC

WIRING DIAGRAM - 3028, 3029 & 3030


FACTORY CONFIGURATION
(CLOCKWISE ROTATION)



ESTOC

WIRING DIAGRAMS - 3028, 3029 & 3030

ESTOC 3PH
TDID/TDDS/TDDSD/TDDP



Without Speed Controls

