

ESTOC EC






WIRING DIAGRAM - 3011 & 3012

CD3011
SINGLE PHASE
EC POWERBOX
FANS - ESTOC

TERMINAL LETTERING

- E - EARTH
- 1 - LIVE
- 2 - NEUTRAL
- 5 - GROUND
- 6 - 0V-10V
- 7 - +10V
- 8 - GROUND
- 9 - 0V-10V
- 10 - +24V

UNIT PN'S:
1PH
UB503559



ESTOC EC

WIRING DIAGRAM - 3011 & 3012

CD3012

SINGLE & THREE PHASE
EC POWERBOX FANS -
ESTOC

TERMINAL LETTERING

PE - EARTH	6 - +10V	10 - +24V
2 - LIVE	7 - GROUND	11 - ENABLE
3 - NEUTRAL	8 - 0V-10V	
4 - GROUND	9 - +24V	
5 - 0V-10V		

UNIT PN'S:

1PH
UB674059
UB674559
3PH
UB805069
UB805669
UB106369

